SCENARIO THREE



OVERVIEW

OVERVIEW		
	The task	Access sloping roof to do an inspection.
	Equipment Available	 Webbing / anchor sling(s) Karabina(s) Full body harness Type 1 Fall Arrest Device (FAD) 10mm Lifeline AS/NZS 1892 compliant ladder

Single tale adjustable lanyard

PHOTO OF AREA

